


Maximizing Product Performance

Troubleshooting:

If operator becomes disengaged:

- Ensure slide operator is inserted into the operator guide rail.
- Slide the operator along the rail until it connects with the inside magnets. **You should feel a single click.**
- This first click indicates that you've engaged two of the four sets of magnets. **Continue to slide the operator until you feel a second click.** This will ensure you have engaged all four sets of magnets.

Visit www.intigral.com to watch the video demonstration of this procedure.



If the blinds are not level:

Click [Here](#) to go to the video

- The Innovia Blind is equipped with a self-leveling feature. Simply lower the blinds fully, then slowly raise the blind to the desired height. Check the level and repeat as needed.

Care Considerations:

- Slide the operator in a gentle and smooth motion to avoid disengaging.
- Keep the operator track clean by removing all dirt and debris from track.