

There is an internal parts change to the strike retainer that the keepers screw into. The old-style retainers are on the left and have longer legs. The new-style retainers are on the right and are modified due to the new style wider strike plate.

If there is a need to replace strike plates on a multi-point astragal that has the old-style strike plates, new plates will be sent. If this happens, you will need to trim the old-style retainers (black line circled) so that the wider strike plate can have room to be properly adjusted. It is possible to trim the tail by using a sharp chisel and hammer. The tail will break off with a good hit of the hammer.

You could replace the strike retainers, but they are hard to get out of the astragal without complete disassembly, and who has time for that!











